National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 05/08/2003

DCA00MA052 File No. 13533	05/21/2000	Bear Creek Town, PA	Aircraft Reg No. N16EJ		Time (Local): 11:28 EDT	
Engine Make/M Aircraft Dam Number of Eng Operating Certificat Name of Ca Type of Flight Opera	odel: British Aerospace / J-310 odel: Allied Signal / TPE331-10 age: Destroyed nes: 2 e(s): On-demand Air Taxi rrier: East Coast Aviation Serv tion: Non-scheduled; Domesti der: Part 135: Air Taxi & Com	oUGR rices c; Passenger Only	Crew Pass	Fatal 2 17	Serious 0 0	Minor/None 0 0
Last Depart. Point: Atlantic City, NJ Destination: Wilkes Barre, PA Airport Proximity: Off Airport/Airstrip		Condition of Light: Weather Info Src: Basic Weather: Lowest Ceiling: Visibility: Wind Dir/Speed: Temperature (°C): Day Weather Observation Facility Instrument Conditions 500 Ft. AGL, Broken 2.50 SM 260 / 003 Kts Temperature (°C): 11 Precip/Obscuration:				
Pilot-in-Command	Age: 34			Flight Ti	me (Hours)	
Certificate(s)/Rating(s) Airline Transport; Multi-engine Land; Single-engine Land; Instrument Ratings Airplane			Total All Aircraft: 8500 Last 90 Days: Unk/Nr Total Make/Model: 5674 Total Instrument Time: UnK/Nr			

The Board's full report is available at http://www.ntsb.gov/publictn/publictn.htm.

On May 21, 2000, about 1128 eastern daylight time (EDT), a British Aerospace Jetstream 3101, N16EJ, operated by East Coast Aviation Services (doing business as Executive Airlines) crashed about 11 miles south of Wilkes-Barre/Scranton International Airport (AVP), Wilkes-Barre, Pennsylvania. The airplane was destroyed by impact and a postcrash fire, and 17 passengers and two flight crewmembers were killed. The flight was being conducted under 14 Code of Federal Regulations (CFR) Part 135 as an on-demand charter flight for Caesars Palace Casino in Atlantic City, New Jersey. An instrument flight rules (IFR) flight plan had been filed for the flight from Atlantic City International Airport (ACY) to AVP.

Brief of Accident (Continued)

DCA00MA052

File No. 13533 05/21/2000 Bear Creek Town, PA Aircraft Reg No. N16EJ Time (Local): 11:28 EDT

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: APPROACH

Findings

1. 1 ENGINE

- 2. (C) PREFLIGHT PLANNING/PREPARATION INADEQUATE FLIGHTCREW
- 3. FLUID, FUEL EXHAUSTION
- 4. (F) IN-FLIGHT PLANNING/DECISION NOT RECOGNIZED FLIGHTCREW
- 5. FUEL SUPPLY INADEQUATE

Occurrence #2: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL

Phase of Operation: APPROACH

Findings

- 6. 1 ENGINE
- 7. (C) FLUID, FUEL STARVATION

Occurrence #3: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: APPROACH

Findings

- 8. AIRCRAFT CONTROL REDUCED
- 9. (F) DIRECTIONAL CONTROL NOT MAINTAINED COPILOT/SECOND PILOT

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Findings

10. TERRAIN CONDITION - GROUND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The flight crews failure to ensure an adequate fuel supply for the flight, which led to the stoppage of the right engine due to fuel exhaustion and the intermittent stoppage of the left engine due to fuel starvation. Contributing to the accident were the flight crew's failure to monitor the airplanes fuel state and the flight crew's failure to maintain directional control after the initial engine stoppage.